Oil Field Environmental Incident Summary

Responsible Party: PETRO-HUNT, L.L.C. **Well Operator:** PETRO-HUNT, L.L.C.

Well Name: Charlson CMSU CTB

Field Name: CHARLSON Well File #:

 Date Incident:
 11/26/2015
 Time Incident:
 09:00
 Facility ID Number:
 400546-01

 County:
 MCKENZIE
 Twp:
 153
 Rng:
 95
 Sec:
 21
 Qtr:
 SE

Location Description:

Submitted By: Derek Enderud Received By:

Contact Person: Derek Enderud

PO BOX 935

BISMARCK, ND 58502

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 50 Barrels 50 Barrels 50 barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/7/2016 Clean Up Concluded: 11/26/2015

Risk Evaluation:

None - within dike and being sucked up.

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Equipment failure, part will be replaced. Dike performed as should keeping all fluid contained. Contaminated material will be hauled to a disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 11/27/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained within the diking according to the report. NDIC retains oversight.